




WHY USE BRIGHT BAY'S NEW HAMMERHEAD MARINE DESCALER FOR OUTBOARD ENGINES?

Marine scale buildup in 4 Stroke Outboard Engine with less than 200 hours of operation in Key West, FL.



Cracked cylinder wall due to overheating from marine scale in the cooling system.

